



Confidential

1(1)

Prepared by  
SEMC/CVDVBA Afrah Sadiq + 46 10 80 12250  
Contents responsible if other than preparer

Document number  
CVDVBA11:039  
Date  
2011-03-02  
Remarks

Revision  
A

Approved by  
SEMC/CVDVBA Johan Wedin Svensk tel +46 10 80 11987

Receiver: Federal Communication Commission and  
Certification and Engineering Bureau  
Industry Canada

**Application: Type number: AAD-3880098-BV,**  
**FCC ID: PY7A3880098,**  
**Canada IC: 4170B-A3880098**

### Statement on Bluetooth hardware

Sony Ericsson mobile phone LT15a (FCC ID: PY7A3880098, IC: 4170B-A3880098) uses the exact same Bluetooth hardware and software as LT15i (FCC ID: PY7A3880097, IC: 4170B-A3880097).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1954-55-04/10, dated 2011-01-14) issued for LT15i also applies for LT15a.

Best regards,

Johan Wedin Svensk  
Manager GSM/UMTS  
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail  
SE-221 88 Lund  
Sweden

Besöksadress • Office address  
Nya Vattentornet  
Lund

Styrelsens säte: Lund  
Registered office: Lund  
Telefon • Telephone  
Nat 010-80 00000  
Int +46 10 80 00000

Momsnr • V.A.T.No: SE556615665801  
Organisationsnr • Reg No: 556615-6658  
Telefax • Telefax  
Nat 010-80 02040  
Int +46 10 80 02040