



Confidential

1(1)

Document number  
CVDVBA11:098  
Date  
2011-03-13  
Remarks

Revision  
A

Prepared by  
SEMC/CVDVBA Afrah Sadiq + 46 10 80 12250  
Contents responsible if other than preparer

Approved by  
SEMC/CVDVBA Johan Wedin Svensk tel +46 10 80 11987

Receiver: Federal Communication Commission and  
Certification and Engineering Bureau  
Industry Canada

**Application: Type number: AAD-3880101-BV,**  
**FCC ID: PY7A3880101,**  
**Canada IC: 4170B-A3880101**

### Statement on Bluetooth hardware

Sony Ericsson mobile phone MT15a (FCC ID: PY7A3880101, IC: 4170B-A3880101) uses the exact same Bluetooth hardware and software as MT15i (FCC ID: PY7A3880100, IC: 4170B-A3880100).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1954-56-04/10, dated 2011-02-18) issued for MT15i also applies for MT15a.

Best regards,

Johan Wedin Svensk  
Manager GSM/UMTS  
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail  
SE-221 88 Lund  
Sweden

Besöksadress • Office address  
Nya Vattentornet  
Lund

Styrelsens säte: Lund  
Registered office: Lund  
Telefon • Telephone  
Nat 010-80 00000  
Int +46 10 80 00000

Momsnr • V.A.T.No: SE556615665801  
Organisationsnr • Reg No: 556615-6658  
Telefax • Telefax  
Nat 010-80 02040  
Int +46 10 80 02040