



Confidential

1(1)

Prepared by
SEMC/CVDVBA Afrah Sadiq + 46 10 80 12250
Contents responsible if other than preparer

Document number
CVDVBA11:313
Date
2011-07-08
Remarks

Revision
A

Approved by
SEMC/CVDVBA Håkan Sjöberg tel +46 10 80 13559

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

**Application: Type number: AAD-3880111-BV,
FCC ID: PY7A3880111,
Canada IC: 4170B-A3880111**

Statement on WLAN hardware

Sony Ericsson mobile phone MK16a (FCC ID: PY7A3880111, IC: 4170B-A3880111) uses the exact same WLAN hardware and software as MK16i (FCC ID: PY7A3880110, IC: 4170B-A3880110).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. TR_2_20797620a_11, dated 2011-06-06) issued for MK16i also applies for MK16a.

Best regards,

Håkan Sjöberg
Acting Manager – HW Verification
Global Type Approval
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
int +46 46 19 41 00