



10 Oppenheimer Street, Park Tamar  
Rehovot, Israel, 76701  
Tel: 972-8-936-31-36, Fax: 972-8-936-59-77

Attn: Reviewing Engineer  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

To whom it may concern:

The AeroScout Location Receiver and label is so small to include the statement as specified in FCC part 15 Sub-part A section 15.19(a)(3):

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason we used the provisions of FCC Part 15 Sub-part A Section 15.19 (a)(5) and we placed this statement in a prominent location in the users manual.

Sincerely,

Reuven Amsalem  
Project Manager  
Bluesoft, Ltd

A handwritten signature in blue ink, appearing to read 'Reuven Amsalem', written over a light blue horizontal line.

Signature:

Date: 05/11/03