

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

The AeroScout Exciter (EX-3100) label is too small to include the statement as specified in FCC part 15 Sub-part A section 15.19(a)(3):

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) This device may not cause harmful interference and

(2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason we used the provisions of FCC Part 15 Sub-part A Section 15.19 (a)(5) and we placed this statement in a prominent location in the users manual.

Sincerely,

Edward Mirodin Senior RF Engineer Aeroscout, Ltd

Hand Signature:

Date: 06/02/2006

10 Oppenheimer St. Park Tamar, Rehovot, Israel, 76701

Tel: 972-8-936-3136 Fax: 972-8-936-5977 www.aeroscout.com