

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

The AeroScout Exciter (EX-3200) FCC ID Q3H EX3200 label is too small to include the statement as specified in FCC part 15 Sub-part A section 15.19(a)(3):

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) This device may not cause harmful interference and

(2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason we used the provisions of FCC Part 15 Sub-part A Section 15.19 (a)(5) and we placed this statement in a prominent location in the users manual.

Sincerely,

Leonid Gnusin Hardware Engineer Aeroscout, Ltd

Signature:

MC

Date: 11/20/2006