



HERMON LABORATORIES

November 18, 2007

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. Timothy R. Johnson, Examining Engineer

RE: your e-mail dated November 14, 2007; Radwin Ltd.

FCC ID:Q3KAMWL1250, ATCB005299

Dear Mr. Johnson,
Please find below the answers to your question.

- 3) The new files Label_location_17746_ODU, Internal_photos_17746_ODU, External_photos_17746_ODU, Setup_photos_17746_ODU, Operational_desciption_17746_ODU were uploaded on November 18, 2007.

Sincerely,

Marina Cherniavsky,

certification engineer
Hermon Laboratories