

Mike Kuo

From: amanda@ccsemc.com.tw on behalf of application@ccsemc.com.tw
Sent: Monday, May 02, 2005 10:25 PM
To: Mike Kuo
Subject: 回信 : FW: Averatec Inc., FCC ID: Q3ZF10DAM, Assessment NO.: AN05T4749, Notice#1
Attachments: 1000 Schem for Module.pdf; 1000 BlkDia for Module.pdf

Dear Mike:

Please refer to below for our reply.

Best Regards,

Amanda

"Mike Kuo" <MKUO@CCSEMC.com>

收件人 : <application@ccsemc.com.tw>

2005/04/29 10:34 AM

副本抄送 :

主旨 : FW: Averatec Inc., FCC ID: Q3ZF10DAM, ?Assessment NO.: AN05T4749, Notice#1

Best Regards

Mike Kuo
Compliance Certification Services
561F Monterey Road
Morgan Hill CA 95037
Tel: (408)463-0885 x: 105
Fax: (408)463-0888
<http://www.ccsemc.com>

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]
Sent: Thursday, April 28, 2005 7:30 PM
To: Mike Kuo
Subject: Averatec Inc., , FCC ID: Q3ZF10DAM, Assessment NO.: AN05T4749, Notice#1

SAR portion:

1) Dipole antenna used for system validation is out of calibration.
Please address this issue and submit the valid calibration report.

Ans: It's because the dipole antenna's calibration cycle is two year.

5/3/2005

Administrative portion:

2) Please provide radio portion of Block Diagram and Schematic Diagram.

[Ans: Please refer as belowing.](#)

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

5/3/2005