



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 1, 2004

RE: Cisco-Linksys, LLC.

FCC ID: Q87-CG2P2WB

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide a higher resolution label exhibit. The FCC ID could not be read.
- 2) There appears to be a problem with presentation of data for data point 1 on page 25, vertical polarity (Frequency and emissions level). Please review and correct as necessary.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.