



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

July 31, 2003

RE: Cisco-Linksys, LLC

FCC ID: Q87-WAP11V28

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The RF exposure calculations appear to be calculated without factoring in the antenna gain. Please review and correct as necessary.
- 2) The Channel 1 plot for the 6 dB bandwidth appears to be missing. Please correct.
- 3) The users manual appears to be missing the information required by 15.21. Please provide information where this may be found in the manual or a corrected manual as necessary.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.