



## *Cisco-Linksys LLC*

*121 Theory Drive Irvine, CA 92617 (USA)*

*Phone: 949-261-1288 Fax: 949-823-3002*

Date: August 13, 2009

To whom it may concern

It is acknowledged by Cisco-Linksys LLC. that the modification list below will be installed to our Model: WVC80N in order to comply with FCC Approval requirements. These modifications will be incorporated into each unit sold and mass production under the rules.

Added copper foil shielding on the PC board, please refer to EUT photos.

1. speaker cable add EMI core and turn one around
2. High frequency cable add EMI core
3. Components position C50 change for 1000pf
4. Components position R23 change for SBK160808T-121-N.
5. Use copper foil to add two ground

Sincerely,

A handwritten signature in black ink, appearing to read "DTennis", written over a horizontal line.

Darrell Tennis/Manager,Regulatory Compliance  
Cisco-Linksys LLC  
TEL:+1 949-910-7048  
FAX:+1-949-823-3002  
E-Mail:dtennis@cisco.com