

# PHOTOS TEST REPORT

FROM



Test of: Aruba Networks, Inc  
to

To: FCC CFR 47 Part 15 Subpart E 15.407

Test Report Serial No.: ARUB206 - 204 205

This report supersedes: NONE

Applicant: Aruba Networks, Inc  
1344 Crossman Ave.  
Sunnyvale, 94089  
USA

Issue Date: 08 January 2016

## **This Test Report is Issued Under the Authority of:**

**MiCOM Labs, Inc.**  
575 Boulder Court  
Pleasanton California 94566  
USA  
Phone: +1 (925) 462-0304  
Fax: +1 (925) 462-0306  
[www.micomlabs.com](http://www.micomlabs.com)




**MiCOM Labs is an ISO 17025 Accredited Testing Laboratory**

## **1. Test Setup Photographs**

### **1.1.1. Test Setup - RE#1 - Radiated Emissions - 3m Chamber**


AP204 TX Spur ant-13B



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.


AP204 TX Spur ant-16



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.


AP204 TX Spur ant-18



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.


AP204 TX Spur ant-19



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.


AP204 TX Spur ant-1b



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.


AP204 TX Spur ant-20w



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

AP205 TX Spur Integral




---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



**1.1.2. Test Setup - RF#2 – Conducted**

RF Conducted



---

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



575 Boulder Court  
Pleasanton, California 94566, USA  
Tel: +1 (925) 462 0304  
Fax: +1 (925) 462 0306  
[www.micomlabs.com](http://www.micomlabs.com)