

Company: Hewlett Packard Enterprise

Product Name: APIN0344 & APIN0345


Report No.: HPEN111 – Test Setup Photos

PHOTOS - TEST SETUP



1. Test Setup Photographs

1.1. Test Setup - DFS - Conducted



HPEN111 AP344 Conducted DFS Setup


This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

1.2. Test Setup - Radiated Emissions




HPEN111 AP344 AP- ANT-13B Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




HPEN111 AP344 AP- ANT-19 Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




HPEN111 AP344 AP- ANT-1W Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




HPEN111 AP344 AP- ANT-20W Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




HPEN111 AP344 AP- ANT-40 Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




HPEN111 AP344 AP- ANT-45 Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



HPEN111 AP344 AP- ANT-48 Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



HPEN111 AP345 Metal Sheet Transmitter Spurious

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

1.3. Test Setup - RF#2 - Conducted



RF Conducted

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



RF Conducted BLE

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com