

Date: 11-June-2024

## **Attestation Letter**

**Federal Communications Commission** 

7435 Oakland Mills Road

Mark Hill Regulatory Compliance Engineer Hewlett Packard Enterprise Compan

Columbia MD 21046

mhill@hpe.com +1 408 8070476 Office

FCC ID: Q9DAPIN0735

To Whom It May Concern:

We, Hewlett Packard Enterprise Company, attest that this device under FCC ID: Q9DAPIN0735 support channel puncturing mechanism.

- 1, The equipment only punctures to optimize network performance and never to avoid licensed incumbents.
- 2, If a channel is punctured in order to optimize network performance, it will continue to use CBP in the punctured region.
- 3, If a licensed incumbent is detected, the equipment will use a complete move of the channel for avoidance.

Hach En

The equipment didn't support bandwidth reduction.

Sign by:

Print Name: Mark Hill

Title: Regulatory Compliance Engineer

Company: Hewlett Packard Enterprise Company

6280 America Center Drive San Jose, CA 95002 USA

arubanetworks.com Page 1 of 1