Company: Aruba Networks

Model Number: WAP3212

Report No.: ARUB189 - WAP 3212 Internal Photographs

**Internal Photographs** 



**INTERNAL EUT PHOTOGRAPHS** 



Aruba Networks WAP3212

Report No.: ARUB189 - WAP 3212 Internal Photographs

Applicant:	Aruba Networks 1344 Crossman Ave. Sunnyvale 94089-1113, United States
Product Function:	Cabin Wireless Access Point Part Number: WAP3212-001-001 RD-FA2066-01
Issue Date:	4th February 2015

## **Issued Under the Authority of:**

MiCOM Labs, Inc. 575 Boulder Court Pleasanton, California 94566 USA Phone: +1 (925) 462-0304 Fax: +1 (925) 462-0306 www.micomlabs.com



MiCOM Labs is an ISO 17025 Accredited Testing Laboratory



le: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
te: 7th Jan 2015
ge: 3 of 13

## 1. Internal Photographs

1.1. Product - Internal




Topside - Controller Board P/N: 13029025-320

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Bottomside - Controller Board P/N: 13029025-320

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




Topside - Power Board P/N: 13029025-420

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



e: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
e: 7th Jan 2015
e: 6 of 13




Bottomside - Power Board P/N: 13029025-420

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



e: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
e: 7th Jan 2015
e: 7 of 13




## Internal assembly - Connector-Board / LED-Board / Antenna-Wiring

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



le: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
ie: 7th Jan 2015
ie: 8 of 13




Internal assembly - Connector-Board / Flex-Cable

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



e: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
e: 7th Jan 2015
e: 9 of 13



Internal assembly - LED-Board / Maintenance-Jack

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



le: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
re: 7th Jan 2015
le: 10 of 13



Internal assembly - Connector-Board / Heatsink with installed Radio-Board (P/N:13029025-701)

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



e: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
e: 7th Jan 2015
e: 11 of 13




Bottomside - Radio-Board P/N: 13029025-701

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



e: Aruba Networks WAP3212
#: ARUB189 - WAP 3212 Internal Photographs
e: 7th Jan 2015
e: 12 of 13



Topside - Radio-Board P/N: 13029025-701

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



575 Boulder Court Pleasanton, California 94566, USA Tel: +1 (925) 462 0304 Fax: +1 (925) 462 0306 www.micomlabs.com