



Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Component side; first half




Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Component side; second half




Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Solder side; first half



Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Solder side; second half



Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Test Setup: Line Conducted




Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Test Setup: Line Conducted



Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Test Setup: Radiated (front of EUT)



Stryker Instruments
TPS Plus new control board
FCC ID: Q9R-5100
06-06-2005

Test Setup: Radiated (back of EUT)

