



8. SETUP PHOTOS


RADIATED RF MEASUREMENT SETUP – Laptop Configuration







RADIATED RF MEASUREMENT SETUP – X Configuration







RADIATED RF MEASUREMENT SETUP – Y Configuration





RADIATED RF MEASUREMENT SETUP – Z Configuration





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT