



Broadcom Corporation, FCC ID: QDS-BRCM1033, Assessment NO.: AN07T7412, ALSO AN07I2261 Notice#1

Inbox
X

 from **tim.dwyer@ccsemc.com** [hide details](#) 10:29 PM (16 hours ago)  **Reply**

to September.Radecki@ccsemc.com,
Sunny.Shih@ccsemc.com,

cc tim.dwyer@ccsemc.com,

date Dec 10, 2007 10:29 PM

subject Broadcom Corporation, FCC ID: QDS-BRCM1033, Assessment NO.: AN07T7412, ALSO AN07I2261 Notice#1

Hello September, Sunny,

Please note that this is a combined notice for AN07T7412 AN07I2261. Please respond to the following item.



Q1: Test report section 7.2.4 shows the DH5 occupancy time above the limit. Please check the data and calculations or repeat the measurements and revise the report.

Best regards,

Tim Dwyer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

 [Reply](#)  [Reply to all](#)  [Forward](#)

 from **September Radecki** <september.radecki@ccsemc.com> [hide details](#) 1:44 PM (1 hour ago)  **Reply**

to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>,
Sunny Shih <sunny.shih@ccsemc.com>,

date Dec 11, 2007 1:44 PM

subject RE: Broadcom Corporation, FCC ID: QDS-BRCM1033, Assessment NO.: AN07T7412, ALSO AN07I2261 Notice#1

Hi Tim,

Below are the replies to your questions on this application.

Q1: Test report section 7.2.4 shows the DH5 occupancy time above the limit. Please check the data and calculations or repeat the measurements and revise the report.

<CCS ANSWER:> Attached please find revised test report.

Best regards,

September

September Radecki
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538
phone: 1-510-771-1090
fax: 1-510-661-0888
September.Radecki@CCSEMC.com <mailto:September.Radecki@CCSEMC.com>

- Show quoted text -

2 attachments — [Download all attachments](#)

 **07U11422-1A FCC IC BLUETOOTH Report_Setup Photos.pdf**
192K [View as HTML](#) [Download](#)

 **07U11422-1A FCC IC BLUETOOTH Report.no photos.pdf**
1510K [View as HTML](#) [Download](#)