

Broadcom Corporation, FCC ID: QDS-BRCM1036, Assessment NO.: AN08T8022 & AN08T8023, Notice#1

Inbox X

from tim.dwyer@ccsemc.com
to Thu.Chan@ccsemc.com
cc Claire.Hoque@ccsemc.com,
tim.dwyer@ccsemc.com

[hide details](#) Jun 27 (3 days ago) | [Reply](#) |

date Fri, Jun 27, 2008 at 5:02 PM
subject Broadcom Corporation, FCC ID: QDS-BRCM1036, Assessment NO.: AN08T8022 & AN08T8023, Notice#1

Hello Thu, Claire,

This notice applies to both applications AN08T8022 and AN08T8023 and so is being sent prior to completion of review for AN08T8023. Although indications are that there are no additional issues, if any are found they will be sent as a separate notice for AN08T8023.

Please reply to the following item:

The SAR report and SAR Photo exhibits indicate the presence of a BT device in this host configuration. The BT device appears to be separated sufficiently that it is not considered "co-located". Although no testing is required if the BT device is already approved as a modular device below the low power threshold, the FCCID for the BT device must also appear on the host product. The label submitted does not include the BT device FCCID. Please confirm that labeling on the host product will meet the requirements for the contained BT device. This C2PC application does not apply to the contained BT device.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer
Technical Reviewer

answer: Broadcom Corporation, FCC ID: QDS-BRCM1036, Assessment NO.: AN08T8022 & AN08T8023, Notice#1 [Inbox](#) X [Priority](#) X

from **Claire Hoque** <claire.hoque@ccsemc.com>
to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com> [hide details](#) 2:24 PM (2 hours ago) [Reply](#) |
cc Chi Tsou <chi.tsou@ccsemc.com>,
Tina Chu <tina.chu@ccsemc.com>
date Mon, Jun 30, 2008 at 2:24 PM
subject answer: Broadcom Corporation, FCC ID: QDS-BRCM1036, Assessment NO.: AN08T8022 & AN08T8023, Notice#1

Hi Tim,

HP confirmed that the following wording will appear on the host system label for the Bluetooth module:

Contains FCC ID: QDS-BRCM1018

Pls let us know if the above answer is sufficient or not.

Thanks,

Claire Hoque
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538, USA
Tel: (510) 771-1123
Fax: (510) 661-0888

-----Original Message-----

From: Timothy M. Dwyer
Sent: Friday, June 27, 2008 2:03 PM
To: Thu Chan
Cc: Claire Hoque; Timothy M. Dwyer
Subject: Broadcom Corporation, FCC ID: QDS-BRCM1036, Assessment NO.: AN08T8022 & AN08T8023, Notice#1

Hello Thu, Claire,

This notice applies to both applications AN08T8022 and AN08T8023 and so is being sent prior to completion of review for AN08T8023. Although indications are that there are no additional issues, if any are found they will be sent as a separate notice for AN08T8023.

Please reply to the following item:

The SAR report and SAR Photo exhibits indicate the presence of a BT device in this host configuration. The BT device appears to be separated sufficiently that it is not considered "co-located". Although no testing is required if the BT device is already approved as a modular device below the low power threshold, the FCCID for the BT device must also appear on the host product. The label submitted does not include the BT device FCCID. Please confirm that labeling on the host product will meet the requirements for the contained BT device. This C2PC application does not apply to the contained BT device.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer
Technical Reviewer