
# 11. SETUP PHOTOS

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP


FOR GFSK & 8PSK MODES; hopping ON & OFF and FOR LE MODE; hopping OFF




Page 103 of 107

## FOR LE MODE:


## **Hopping ON**






Page 104 of 107

#### **RADIATED RF MEASUREMENT SETUP**






Page 105 of 107




COMPLIANCE CERTIFICATION SERVICES (UL CCS) 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 106 of 107

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





## **END OF REPORT**

#### Page 107 of 107

COMPLIANCE CERTIFICATION SERVICES (UL CCS)FORM NO: CCSUP4701D47173 BENICIA STREET, FREMONT, CA 94538, USATEL: (510) 771-1000FAX: (510) 661-0888This report shall not be reproduced except in full, without the written approval of UL CCS.