

Report No.: 0303815
Model No.: 1861

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement


MKA 16.800 msec

REF 97.0 dB μ V

AT 10 dB

.02 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By:

(Signature)
(Cargi)

Date: 15-3-03

Checked By:

(Signature)
(Anthony Chen)

Date: 17/3/03

Test Result : Pass / Fail / NA

CENTER 49.862 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec


Report No.: 0303815
Model No.: 1861

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

hp MKR 1.3500 msec
REF 97.0 dBμV AT 10 dB -.49 dB

PEAK
LOG
10
dB/

VA SB
SC FC
CORR



Tested By: [Signature]
(Chang Li)

Date: 15-3-03

Checked By: [Signature]
(Andrew Chan)

Date: 17/3/03

Test Result : Pass / Fail / NA

CENTER 49.862 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 030345
Model No.: 1861

Pursuant to FCC Part 15 Section 15. 255 Emissions Requirement


MKA 525.00 μ sec

REF 97.0 dB μ V

AT 10 dB

-.11 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: *[Signature]*

(Gongli)

Date: 15-3-03

Checked By: *[Signature]*

(Anthony Chan)

Date: 17/3/03

Test Result: Pass / Fail / NA

CENTER 49.862 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec