

Amendment to FCC Part 22/24 Compliance Test Report

Test Report no.:	Amendment to Oulu_FCC_0526_02.doc	Date of Report:	11.08.2005
Number of pages:	2	Customer's Contact person:	Kai Niskala
Testing laboratory:	TCC Nokia Oulu Laboratory P.O. Box 300 Yrttpellontie 6 FIN-90230 OULU, FINLAND Tel. +358 (0) 7180 08000 Fax. +358 (0) 7180 58300	Client:	Nokia Corporation P.O. Box 300 Yrttpellontie 6 FIN-90230 OULU, FINLAND Tel. +358 (0) 7180 08000 Fax. +358 (0) 7180 58300
FCC listing no.:	185671		
IC recognition no.:	4542		
Tested devices/ accessories:	Phone RM-84 / battery BLC-5C, AC-charger AC-3E and headset HS-3		
FCC ID:	QFXRM-84	IC:	661Z-RM84
Supplement reports:	-		
Testing has been carried out in accordance with:	CFR 47, FCC rules Parts 22 and 24, TIA-603-B-2002 and IC standards RSS-132 and RSS-133. Deviations, modifications or clarifications (if any) to above mentioned documents are written in each section under "Test method and limit".		
Documentation:	The test report must always be reproduced in full; reproduction of an excerpt only is subject to written approval of the testing laboratory. The documentation of the testing performed on the tested devices is archived for 15 years at TCC Nokia.		
Test Results:	The EUT complies with the requirements in respect of all parameters subject to the test. The test results relate only to devices specified in this document.		
Date and signature for the contents:	11-08-2005		

Erik Rundgren, Test System Manager

1. Summary for FCC Part 22/24 Compliance Test Report

Test report Oulu_FCC_0526_02.doc has got following incorrect information.

On page two the phone DUT information refers to wrong DUT, as follows:

Product	Type	SN	HW	MV	SW	DUT
Phone	RM-99	004400/69/169943/1	3993	-	1.0519.5.1	30390

Correct DUT information is:

Product	Type	SN	HW	MV	SW	DUT
Phone	RM-84	004400/69/169946/4	3991	-	1.0519.0.2	30389

(End of the amendment report)