

Response to TCB Findings

1. The shielded antenna cables with 6 ferrites on them needs to be addressed in the user's manual as required by 15.27.

Response: A new user's manual with detail of antenna cable with ferrites (see conveyAntInstall13.pdf , page 20).

2. Please extract the test set-up pictures from the report and submit as a separate file

Response: Supplied.