

### **Extract from response to TCB questions**

*8. Please provide the tune-up procedure as required by 2.1033(c)(9).*

**Output level is set via software up to the value at which the report data was taken. Airvana indicates this device has no tune-up procedure but output is verified after installation via a PA offset calibration. Please let me know if you need more information on this calibration.**