

## Reasons for re-testing of Corinex Intelligent PowerNet Ethernet Adapter

There were a few changes between the first tested model, report nbr. M/EMV-02/253 and the model which will be marketed and tested report nbr. M/EMV-02/277.

1. Changes in casing material and design
2. Few PCB layout changes due to
  - casing design changes accompanied with changes of LED-positions
  - changing of some components, e.g. from wired to SMD
  - changing of line transformer
  - some position changes

There were no changes in circuitry.