

VOLKSWAGEN

AKTIENGESELLSCHAFT

GROUP AFTER SALES



## Quickstart manual for the use of Group Service Key Software

- A** If you are using the **Dealer Portal**, you can download the Group Service Key software via the following URL:

<https://mirrorserver-cert.cpn.vwg/jctmirrorserver/dav/BTAC/Trade-Retail/Tools/GroupServiceKey/DP>

- B** If you are using the **Group Retail Portal**, you can download the Group Service Key software via the following URL:

<https://mirrorserver-cert.cpn.vwg/jctmirrorserver/dav/BTAC/Trade-Retail/Tools/GroupServiceKey/GRP>

- i** After the download has finished, please plug in your Service Key reader and install the Setup.exe file with Windows administrator rights. In case you don't have administrator rights, please contact your local administrator for assistance.



Quickstart manual  
Service Key Reader



Required components



Connect the device to power supply and PC



Device in operation



#### Regulatory statement United States

"Class B: (Section 15.105) FEDERAL COMMUNICATIONS COMMISSION INTERFERENCE STATEMENT This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures: -Reorient or relocate the receiving antenna. - Increase the separation between the equipment and receiver. -Connect the equipment into an outlet on a circuit different from that to which the receiver is connected. -Consult the dealer or an experienced radio/ TV technician for help. (Section 15.21) CAUTION: Any changes or modifications not expressly approved by the grantee of this device could void the user's authority to operate the equipment."

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation."

#### Regulatory statement Canada

Canada, Industry Canada (IC) Notices This Class B digital apparatus complies with Canadian ICES-003 and RSS-210. Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device. Canada, avis d'Industry Canada (IC) Cet appareil numérique de classe B est conforme aux normes canadiennes ICES-003 et RSS-210. Son fonctionnement est soumis aux deux conditions suivantes : (1) cet appareil ne doit pas causer d'interférence et (2) cet appareil doit accepter toute interférence, notamment les interférences qui peuvent affecter son fonctionnement."