

## Chris Harvey EMC

---

**From:** Chris Harvey EMC [chrisharveyemc@comcast.net]  
**Sent:** Monday, November 17, 2003 3:21 PM  
**To:** Marianne Bosley (mbosaley@metlabs.com)  
**Cc:** 'Alvin Ilarina'  
**Subject:** BeamReach FCC Application review comments, Request for Technical Information

The following items must be corrected before this application can continue to be reviewed for FCC Compliance:

- 1) The photos submitted do not show back sides of boards, and the front side photos are out of focus (Base Module Photos). Please resubmit corrected photographs.
- 2) Please provide an Emission Designator.
- 3) Please submit a Label location drawing.
- 4) Please correct the following items in the test report: Equipment code is TNB; Emission Designator; Mode of Operation; Modifications section details from the applicant.
- 5) Report Section A Spurious Emissions at Antenna Terminals, per 27.53 (a)(4) the bandwidth used is supposed to be 1MHz or greater. The report seems to document a Resolution Bandwidth of 100 kHz in each plot. This needs to be corrected.
- 6) Report Section major headers and then the next header do not match (i.e. Test Equipment section VIII vs. VI.)

Please reply as soon as possible so that the application review can be completed.

Best regards,

Chris Harvey  
Chris Harvey EMC Consultants, LLC  
cell 443-622-3300