


Appendix C. Set up Photograph

Conducted Emission

Mode 1~3



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : May 18, 2006
Report Version : Rev. 01





SIDE VIEW

Mode 4




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : May 18, 2006
Report Version : Rev. 01





REAR VIEW



SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : May 18, 2006
Report Version : Rev. 01



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : May 18, 2006
Report Version : Rev. 01