
FCC TEST REPORT Report No.: F300803

## 1.1. Photographs of Conducted Powerline Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : QS3WBFZP1

Page No. : 1 of 3

Issued : Dec. 04, 2003

FCC TEST REPORT **Report No.: F300803** 



SIDE VIEW

FCC ID : QS3WBFZP1 SPORTON International Inc. TEL: 886-2-2696-2468

Page No. : 2 of 3 Issued : Dec. 04, 2003 FAX: 886-2-2696-2255

FCC TEST REPORT Report No.: F300803

## 1.2. Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 



**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

Issued : Dec. 04, 2003

Page No. : 3 of 3

: QS3WBFZP1

FCC ID