



**NOTICE**  
WAFFER BREAKAGE HAZARD  
Vacuum Bagging May Cause  
Wafer Breakage  
Do Not Vacuum Bag Shipper

**CAUTION**  
WAFFER SENSITIVE TO  
TEMPERATURE DURING STORAGE  
WAFFER MAY BE DAMAGED AND  
WARRANTY VOIDED BY STORING  
OUTSIDE OF RECOMMENDED  
RANGE  
STORE WAFFER BETWEEN  
15C (59F) TO 40C (104F) AT ALL  
TIMES. SEE OWNER'S MANUAL.



02-AT-850-3300 1/0



KLA   
SensArray Division

RESET



# NOTICE

## WAFER BREAKAGE HAZARD

Vacuum Bagging May Cause  
Wafer Breakage


Do Not Vacuum Bag Shipper

# CAUTION



WAFER SENSITIVE TO  
TEMPERATURE DURING STORAGE

WAFER MAY BE DAMAGED AND  
WARRANTY VOIDED BY STORING  
OUTSIDE OF RECOMMENDED  
RANGE

STORE WAFER BETWEEN  
15C (59F) TO 40C (104F) AT ALL  
TIMES. SEE OWNER'S MANUAL.



0548685-000 AD



SensArray Division