

Ole Myrtue

January 29, 2004

## **Changes in QTKRH-36**

### RF

The antenna has been re-tuned for better matching.

### BB

Some resistor changes related to the internal power regulator and LED drivers

### Mechanics

No changes.

### Other

Second source VCO in PLL – electrically identical, no changes to matching component.

## **Results of internal review (FCC focus)**

Radiated power output, Field strength of spurious radiation, RF Exposure