

From: "david waitt \ (Yahoo\)" <dw8p1@yahoo.com>

Subject: RE: Review of Application Airespace Inc. FCC ID: QTZ1300 after recent uploads

To: "Timothy R. Johnson" <TRJ@adelphia.net>

Hey Tim,

Actually I verified this morning that the amp is NOT tunable after it leaves the factory.

Manual guy did not know this assumed it was "Field Tunable".

This makes a lot more sense to me haveing seen the amp... who is going to tweak up a 5.8 GHz amp in the field?

The other references to internal are also errors left over from the previous life of the manual.