



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

January 20, 2004

RE: Airespace

FCC ID: QTZWN1200ABG

I have a few comments on the above referenced Application.

General

- 1) FYI...Your response to item #5 stated that a Class A DoC has been issued for this device. Note that only a class B device may have a DoC report issued. A Class A report would be a Verification.

15.247

- 2) The values in the paragraph (regarding power) appear lower than the measured power. Please explain.
- 3) The sample calculation on the body of page 28 does not match the corrected. tables. Please correct.

UNII

- 4) The block diagram provided still shows a switch in the RF output lines. Please provide the correct block diagram.
- 5) Please adjust the correspondence for question 16 as discussed with the last project.
- 6) The new plot on the bottom of page 45 appears mislabeled. Please review.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.