

To: "Timothy R. Johnson" <tjohnson@AmericanTCB.com>
Subject: Review of Microlink Communications Inc., FCC ID: QVZ10020000 after recent uploads

Dear Timothy,

Thanks for your kindly advise.

As per your review comments, please see the explanation below:

- 1) Please find the revised manual attached per your requirement for your reviewing.
- 2) Please find the block diagram below the following description:
 - The output power is +15dBm at the PA.
 - The loss between PA and Antenna is about 3dB.
 - Each loss of the components is listed below:
 - BPF: ~1.8dB
 - LPF: ~0.3dB
 - RF Switch: ~0.5dB
 - Other loss: ~0.4dB.
 - Therefor, the output power is about 12dBm at the antenna.

Fax: (+886-3) 519-1410
jchu@itslabtest-twn.com
www.etlsemko.com



[Installation guide12.pdf](#)