

FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page <u>1</u> of <u>10</u>



FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page \_\_\_\_\_\_ of \_\_\_\_\_

## 2.7 Photos of Conduction Test

Antenna 2 : Antenna gain is 2dBi








FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page <u>3</u> of <u>10</u>

Antenna 3 : Antenna gain is 5dBi








Antenna 6 : Antenna gain is 7.5dBi







## 3.7 Photos of Open Site

Antenna 2 : Antenna gain is 2dBi







FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page <u>6</u> of <u>10</u>





FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page <u>7</u> of <u>10</u>




Antenna 3 : Antenna gain is 5dBi





Antenna 3 : Antenna gain is 5dBi







FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page <u>9</u> of <u>10</u>



Antenna 6 : Antenna gain is 7.5dBi





FCC ID : QVZ58905933 Report No. : ER04-10-056FRF Page <u>10</u> of <u>10</u>

Antenna 6 : Antenna gain is 7.5dBi



