

## Chris Harvey

---

**From:** Chris Harvey [charvey@ieee.org]  
**Sent:** Wednesday, May 28, 2008 2:15 PM  
**To:** 'EASADMIN@fcc.gov'  
**Cc:** 'Claire Hoque'; 'Christine Vu'; 'charvey-tcb@ccsemc.com'; 'Mike Kuo'  
**Subject:** Assistance needed to Correct Typos for FCC ID: QPW58500  
**Attachments:** RP49755JD06A Receive On 5-13-08.pdf

Dear FCC,

I was involved in the review and TCB Granting of FCC ID: QPW58500 on April 10, 2008. The test report submitted in the application had inadvertently included typos in the test equipment used and the measurement method for the RF Power Measurement which led to the grant listing of the incorrect power level. This error was discovered after the grant was issued, at which time CCS-TCB requested a Post-Grant sample of the EUT for confirmation of the measurement.

The Test Lab has re-issued the test report with corrections to clarify the output power test method description. It is our understanding that there are no changes to any of the reported measurements. The revised test report is attached. We will like to upload revised documents for this filing and re-issue the Grant to list the correct 0.457W output power.

Please place this filing into audit mode so we can make this change to correct the typos and revise the power based on that typo.

Best regards,

Chris Harvey