

TUV SUD BABT TCB  
Octagon House,  
Segensworth Road,  
Fareham,  
Hampshire,  
PO15 5RL

2016-02-08

Ref: Justification for placing the FCC ID in the manual

**FCC ID: QZ3BAHA5POWER**

To whom it may concern:

We, **Cochlear Bone Anchored Solutions AB**, hereby state that the text as defined in 15.19(a)(3) is too large to be placed on the label of the Device. Therefore it will be placed in a prominent location of the User Guide.

Additionally, we also hereby state that there is one main reason why device state above does not have FCC ID:

- 1) The device is too small to have visible text (smaller than 4-6 points)

Therefore, FCC ID is included in the user manual will be supplied together with the device.

Sincerely,



---

By: Jon Callerfjord

Title: Director Q&R

Company: Cochlear Bone Anchored Solutions AB

Telephone / Fax: +46 (0)31 792 44 14 / +46 (0)31 792 46 95

e-mail: [jcallerfjord@cochlear.com](mailto:jcallerfjord@cochlear.com)