BURY GMBH & CO. KG ROBERT-KOCH-STRASSE 1-7 D-32584 LÖHNE



Date:

03.07.2012

FCC ID:

QZ9-TPKM820

Subject: Compliance Statement in Car Manual

Dear Sirs.

Our products with the above FCC ID are marketed together with cars, where it's operation is included in the individual owner's manual of the car.

We hereby assure that the following caution statement as per CFR 47, §15.21 is included in a prominent location of the owner's manual of the cars:

The title "CAUTION TO USERS" or "FCC WARNING": "NOTE" or relevant title and "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

In addition, we also assure that the following statements is also included in a prominent location in the manual as per CFR 47, §15.19(a)(3):

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.



If you have any questions, please feel free to contact me at the address shown below.

Yours sincerely,

Signatory

Name:

Position: CompanyAdress:

Tel/Fax: E-Mail:

Christoph Koston **EMC & Validation** Bury GmbH & Co. KG Robert-Koch-Streße 1-7

32584 Löhne 057329706284

koston@bury.com