



11734 South Election Drive  
Suite 200  
Draper, Utah 84020  
(801) 523-3100

---

To: Federal Communications Commission  
445 12<sup>th</sup> Street, SW  
Washington, DC 20554

Date: 09/22/2010

Re: Letter of Changes FCC ID: R33C4SR250Z

---

We are informing the interested parties regarding changes made to the following product model number.

C4-SR250-Z-B – New part number C4-SR250B-Z-B

Changes in RF section of the product are:

- 1) Additional filtering added to the DC power supply that supplies the RF radio circuitry.
- 2) RF output balun component value change that improves RF signal integrity.
- 3) Output harmonic filter was added to the PCB layout, but after testing showed it was not needed, the parts were changed to Do Not Stuff.

Thank you,

A handwritten signature in black ink, appearing to read "Ajit Sampalli".

Ajit Sampalli  
Compliance Engineer  
Control4 Technologies