
3. Internal Photograph of EUT

Brand Name: Coolpad; Model Name: Coolpad 5560S

Report No.: EP452702



TEL: 86-755- 3320-2398 FCC ID: R38YL5560S

Page Number : 12 of 31
Report Issued Date : Aug. 12, 2014



Report No.: EP452702




TEL: 86-755-3320-2398 FCC ID: R38YL5560S

Page Number : 13 of 31 Report Issued Date: Aug. 12, 2014





Report No.: EP452702



TEL: 86-755-3320-2398 FCC ID: R38YL5560S

Page Number : 14 of 31 Report Issued Date: Aug. 12, 2014






TEL: 86-755-3320-2398 FCC ID: R38YL5560S Page Number : 15 of 31
Report Issued Date : Aug. 12, 2014


Report No.: EP452702


Brand Name: Coolpad; Model Name: Coolpad 5560S



TEL: 86-755-3320-2398 FCC ID: R38YL5560S


Page Number : 16 of 31 Report Issued Date: Aug. 12, 2014






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 17 of 31
Report Issued Date : Aug. 12, 2014






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 18 of 31
Report Issued Date : Aug. 12, 2014



Report No.: EP452702




TEL: 86-755-3320-2398 FCC ID: R38YL5560S

: 19 of 31 Page Number Report Issued Date: Aug. 12, 2014



Report No.: EP452702




TEL: 86-755-3320-2398 FCC ID: R38YL5560S

: 20 of 31 Page Number Report Issued Date: Aug. 12, 2014



Brand Name: Coolpad; Model Name: Coolpad 5560S

Report No.: EP452702




TEL: 86-755-3320-2398 FCC ID: R38YL5560S

: 21 of 31 Page Number Report Issued Date: Aug. 12, 2014




Report No.: EP452702



TEL: 86-755-3320-2398 FCC ID: R38YL5560S


: 22 of 31 Page Number Report Issued Date: Aug. 12, 2014

Report No.: EP452702




TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 23 of 31
Report Issued Date : Aug. 12, 2014

Report No.: EP452702




TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 24 of 31
Report Issued Date : Aug. 12, 2014

Report No.: EP452702




TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 25 of 31
Report Issued Date : Aug. 12, 2014

Report No.: EP452702



TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 26 of 31
Report Issued Date : Aug. 12, 2014
Report Version : Rev. 01


Report No.: EP452702



TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 27 of 31
Report Issued Date : Aug. 12, 2014




Report No.: EP452702



TEL: 86-755- 3320-2398 FCC ID: R38YL5560S Page Number : 28 of 31
Report Issued Date : Aug. 12, 2014




Report No.: EP452702



TEL: 86-755-3320-2398 FCC ID: R38YL5560S

: 29 of 31 Page Number Report Issued Date: Aug. 12, 2014


Report No.: EP452702



TEL: 86-755-3320-2398 FCC ID: R38YL5560S Page Number : 30 of 31
Report Issued Date : Aug. 12, 2014



Report No.: EP452702



TEL: 86-755-3320-2398 FCC ID: R38YL5560S

: 31 of 31 Page Number Report Issued Date: Aug. 12, 2014