

Date: 2019/10/22

Federal Communications Commission  
Office of Engineering and Technology  
Equipment Authorization Division  
7345 Oakland Mills Road  
Columbia, Maryland 21046

Subject: FCC Class II Permissive change for FCC ID:R38YLCP3648A

To Whom It May Concern,

This is to request a Class II Permissive change for FCC ID:R38YLCP3648A, granted on 2019.08.01.

We, Yulong Computer Telecommunication Scientific (Shenzhen) Co., Ltd, declare on our sole responsibility for the product of cp3648AT as below:

The differences between cp3648A and cp3648AT are:

Support of Volte/IMS (cp3648AT Yes, cp3648A No),

Update Model name ( cp3648AT )

Android Client ID and User experience changed from the original Sprint to TMO

RSU is removed

Except differences above, the others are all the same. No hardware changes.

According to the change detail, the test items below were performed.

1. SAR

Spot check worst cases.

2.HAC RF & T-Coil

Add tests of Volte for T-Coil.

Use original test data for RF.

Thank you.

Sincerely,

Contact Name: yanting,chen

Title:Product Manager

Company Name:Yulong Computer Telecommunication Scientific (Shenzhen) Co., Ltd

Company address:Building B, Boton Science Park, Chaguang Road, Xili Town, Nanshan District, Shenzhen, P.R.C



Signature: