



5777 West Maple Road, Suite 140
West Bloomfield, Michigan 48322
Phone 248-737-4110
Facsimile 248-737-4130

September 16, 2004

Federal Communications Commission

To Whom It May Concern:

I have been informed by our ACS Testing Lab that the power level of the transmitter must be reduced in or to comply with regulations. The statement in the report reads:

"Modifications were required in order to bring the unit into compliance with the radiated spurious emission limits.

- 1) The RF output power was lowered to setting number 3 of the power setting list."

You can be assured that I will make the necessary changes in the manufacturing process to make sure that the RF output power setting is set to the proper setting as indicated in the above statement.

Sincerely,

Franklin J. Desrochers
Vice President / Chief Technology Officer