


# JBP TEST SETUP PHOTOS

## 1 Radiated Field Strength Measurement




30 MHz-1 GHz (USB Test Mode)



Above 1 GHz (USB Test Mode)



30 MHz-1 GHz (Camera Test Mode)




1 GHz-6 GHz (Camera Test Mode)

## 2 Conducted Emission



USB Test Mode



Camera test mode