


INTERTEK TESTING SERVICES

Report No.: 03/5084
 Model No.: 13000A
 13000

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement

hfg MKR 36.500 msec
 REF -20.0 dBm AT 10 dB .00 dB

PEAK
 LOG
 10
 dB/



VA SB
 SC FC
 CORR

Tested By: LK
 (Korrr Wong)

Date: 17/9/03

Checked By: [Signature]
 (Vick)

Date: 18/9

Test Result: Pass / Fail / (NA)

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 100 msec

Report No.: 0315084
Model No.: 13000V
13000

Pursuant to FCC Part 15 Section 15. 255 Emissions Requirement


MKA 36.300 msec

REF -20.0 dBm

AT 10 dB

.26 dB

PEAK
LOG
10
dB/



Tested By: (Signature)
(Terrell Wong)

Date: 17/9/03

Checked By: (Signature)
(T. Wong)

Date: 18/9/03

Test Result: Pass / Fail (NA)

CENTER 49.861 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 60.0 msec

Report No.: 0315084
 Model No.: 13000W
 13000

Pursuant to FCC Part 15 Section 15, 255 Emissions Requirement

MKFR 1.6500 msec

REF -20.0 dBm

AT 10 dB


- .41 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By:

KL
Kenneth Wong

Date:

17/9/03

Checked By:

[Signature]
(Vick)

Date:

18/9/03

Test Result : Pass / Fail (NA)

CENTER 49.861 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 60.0 msec

INTERTEK TESTING SERVICES


Report No.: 0315084
Model No.: ~~13000~~
13000

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKR 600.00 μ sec
-.56 dB

REF -20.0 dBm AT 10 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: LR
(Kenneth Wong)
Date: 17/9/03

Checked By: [Signature]
(1000)
Date: 18/9/03

Test Result: Pass / Fail / NA

CENTER 49.861 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 60.0 msec