FCC TEST REPORT Report No.: F341605

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

 SPORTON International Inc.
 FCC ID
 : RENFC-AL2011PW

 TEL: 886-2-2696-2468
 Page No.
 : 1 of 3

FAX: 886-2-2696-2255 Issued Date : Jun. 24, 2003

FCC TEST REPORT Report No. : F341605



SIDE VIEW

SPORTON International Inc. FCC ID : RENFC-AL2011PW

TEL: 886-2-2696-2468

Page No. : 2 of 3 Issued Date : Jun. 24, 2003 FAX: 886-2-2696-2255

FCC TEST REPORT Report No.: F341605

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID : RENFC-AL2011PW

Page No. : 3 of 3

Issued Date : Jun. 24, 2003