FCC TEST REPORT Report No.: F341604

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.




FRONT VIEW



REAR VIEW

SPORTON International Inc. FCC ID : RENFC-AL2014PW

TEL: 886-2-2696-2468 Page No. : 1 of 3 FAX: 886-2-2696-2255 Issued Date : Jul. 25, 2003 FCC TEST REPORT Report No.: F341604



SIDE VIEW

SPORTON International Inc. FCC ID : RENFC-AL2014PW


TEL: 886-2-2696-2468 Page No. : 2 of 3 FAX: 886-2-2696-2255 Issued Date : Jul. 25, 2003 FCC TEST REPORT Report No.: F341604

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. FCC ID : RENFC-AL2014PW

TEL: 886-2-2696-2468 Page No. : 3 of 3 FAX: 886-2-2696-2255 Issued Date : Jul. 25, 2003