

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1



Photo 2

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

	Horizontal	Vertical
Band edge / other	X	Y
2nd harmonic	Y	Z
Below 1GHz	With Cradle Type2	With Cradle Type2

X-axis



With Cradle Type1



Y-axis



With Cradle Type2



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124