


Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 746 of 833

802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 747 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 748 of 833

802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 749 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 750 of 833

802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 751 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 752 of 833

6.2.2 EMask

802.11ax(HEW20)_LCH_6435MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6435MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 753 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 754 of 833

802.11ax(HEW20)_MCH_6475MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6475MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 755 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 756 of 833

802.11ax(HEW20)_HCH_6515MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6515MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 757 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 758 of 833

802.11ax(HEW40)_LCH_6445MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6445MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 759 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 760 of 833

802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 761 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 762 of 833

802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 763 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 764 of 833

6.2.3 EMask

802.11ax(HEW20)_LCH_6535MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 765 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 766 of 833

802.11ax(HEW20)_MCH_6695MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6695MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 767 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 768 of 833

802.11ax(HEW20)_HCH_6855MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6855MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 769 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 770 of 833

802.11ax(HEW40)_LCH_6565MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6565MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 771 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 772 of 833

802.11ax(HEW40)_MCH_6685MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6685MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 773 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 774 of 833

802.11ax(HEW40)_HCH_6845MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6845MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 775 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 776 of 833

802.11ax(HEW80)_LCH_6625MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6625MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 777 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 778 of 833

802.11ax(HEW80)_MCH_6705MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_MCH_6705MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 779 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 780 of 833

802.11ax(HEW80)_HCH_6785MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6785MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 781 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 782 of 833

802.11ax(HEW160)_MCH_6665MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6665MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 783 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 784 of 833

6.2.4 EMask

802.11ax(HEW20)_LCH_6895MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6895MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 785 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 786 of 833

802.11ax(HEW20)_MCH_6995MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6995MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 787 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 788 of 833

802.11ax(HEW20)_HCH_7115MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_7115MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 789 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 790 of 833

802.11ax(HEW40)_LCH_6925MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6925MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 791 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 792 of 833

802.11ax(HEW40)_MCH_7005MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_7005MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 793 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 794 of 833

802.11ax(HEW40)_HCH_7085MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_7085MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 795 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 796 of 833

802.11ax(HEW80)_LCH_6945MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6945MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 797 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 798 of 833

802.11ax(HEW80)_HCH_7025MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_7025MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 799 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 800 of 833

802.11ax(HEW160)_MCH_6985MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6985MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 801 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 802 of 833

6.2.5 EMask

802.11ax(HEW20)_HCH_6875MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6875MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 803 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 804 of 833

802.11ax(HEW40)_HCH_6885MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6885MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 805 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 806 of 833

802.11ax(HEW80)_HCH_6865MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6865MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 807 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 808 of 833

802.11ax(HEW160)_HCH_6825MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6825MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 809 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 810 of 833

6.2.6 EMask

802.11ax(HEW40)_HCH_6525MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6525MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 811 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 812 of 833

802.11ax(HEW80)_HCH_6545MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6545MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 813 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 814 of 833

802.11ax(HEW160)_HCH_6505MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6505MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 815 of 833



Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 816 of 833

7. Contention Based Protocol

7.1 Test Result

Test Mode	Antenna	Channel	Interference Frequency [MHz]	Status	AWGN Power [dBm]	Gain [dB]	Adjusted Power [dBm]	Limit [dBm]	Detection Rate		Verdict
									Result [%]	Limit [%]	
11AX20SISO	Ant1	6135	6135	OFF	-74.71	2.85	-77.56	-62	100	90	Pass
11AX20SISO	Ant1	6135	6135	Minimal	-75.67	2.85	-78.52	-62	10	-	-
11AX20SISO	Ant1	6135	6135	ON	-85	2.85	-87.85	-62	-	-	-
11AX20SISO	Ant1	6455	6455	OFF	-71.71	1.75	-73.46	-62	100	90	Pass
11AX20SISO	Ant1	6455	6455	Minimal	-74.76	1.75	-76.51	-62	10	-	-
11AX20SISO	Ant1	6455	6455	ON	-85	1.75	-86.75	-62	-	-	-
11AX20SISO	Ant1	6695	6695	OFF	-71.55	2.48	-74.03	-62	100	90	Pass
11AX20SISO	Ant1	6695	6695	Minimal	-72.04	2.48	-74.52	-62	0	-	-
11AX20SISO	Ant1	6695	6695	ON	-85	2.48	-87.48	-62	-	-	-
11AX20SISO	Ant1	7015	7015	OFF	-72.37	1.88	-74.25	-62	100	90	Pass
11AX20SISO	Ant1	7015	7015	Minimal	-73.40	1.88	-75.28	-62	0	-	-
11AX20SISO	Ant1	7015	7015	ON	-85	1.88	-86.88	-62	-	-	-
11AX160SISO	Ant1	6185	6110	OFF	-63.87	2.85	-66.72	-62	100	90	Pass
11AX160SISO	Ant1	6185	6185	OFF	-66.52	2.85	-69.37	-62	100	90	Pass
11AX160SISO	Ant1	6185	6260	OFF	-64.46	2.85	-67.31	-62	100	90	Pass
11AX160SISO	Ant1	6185	6110	Minimal	-65.82	2.85	-68.67	-62	0	-	-
11AX160SISO	Ant1	6185	6185	Minimal	-66.61	2.85	-69.46	-62	10	-	-
11AX160SISO	Ant1	6185	6260	Minimal	-65.09	2.85	-67.94	-62	0	-	-
11AX160SISO	Ant1	6185	6110	ON	-82	2.85	-84.85	-62	-	-	-
11AX160SISO	Ant1	6185	6185	ON	-82	2.85	-84.85	-62	-	-	-
11AX160SISO	Ant1	6185	6260	ON	-82	2.85	-84.85	-62	-	-	-
11AX160SISO	Ant1	6505	6430	OFF	-64.35	2.48	-66.83	-62	100	90	Pass
11AX160SISO	Ant1	6505	6505	OFF	-64.36	2.48	-66.84	-62	90	90	Pass
11AX160SISO	Ant1	6505	6580	OFF	-63.33	2.48	-65.81	-62	100	90	Pass
11AX160SISO	Ant1	6505	6430	Minimal	-65.64	2.48	-68.12	-62	0	-	-
11AX160SISO	Ant1	6505	6505	Minimal	-65.07	2.48	-67.55	-62	0	-	-
11AX160SISO	Ant1	6505	6580	Minimal	-65.21	2.48	-67.69	-62	0	-	-
11AX160SISO	Ant1	6505	6430	ON	-82	2.48	-84.48	-62	-	-	-
11AX160SISO	Ant1	6505	6505	ON	-82	2.48	-84.48	-62	-	-	-
11AX160SISO	Ant1	6505	6580	ON	-82	2.48	-84.48	-62	-	-	-
11AX160SISO	Ant1	6825	6750	OFF	-62.06	2.48	-64.54	-62	100	90	Pass
11AX160SISO	Ant1	6825	6825	OFF	-66.48	2.48	-68.96	-62	90	90	Pass
11AX160SISO	Ant1	6825	6900	OFF	-66.34	2.48	-68.82	-62	90	90	Pass
11AX160SISO	Ant1	6825	6750	Minimal	-64.39	2.48	-66.87	-62	0	-	-



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 817 of 833

11AX160SISO	Ant1	6825	6825	Minimal	-66.85	2.48	-69.33	-62	0	-	-
11AX160SISO	Ant1	6825	6900	Minimal	-66.82	2.48	-69.30	-62	10	-	-
11AX160SISO	Ant1	6825	6750	ON	-82	2.48	-84.48	-62	-	-	-
11AX160SISO	Ant1	6825	6825	ON	-82	2.48	-84.48	-62	-	-	-
11AX160SISO	Ant1	6825	6900	ON	-82	2.48	-84.48	-62	-	-	-
11AX160SISO	Ant1	6985	6910	OFF	-66.71	1.88	-68.59	-62	100	90	Pass
11AX160SISO	Ant1	6985	6985	OFF	-61.02	1.88	-62.90	-62	100	90	Pass
11AX160SISO	Ant1	6985	7060	OFF	-65.60	1.88	-67.48	-62	90	90	Pass
11AX160SISO	Ant1	6985	6910	Minimal	-66.83	1.88	-68.71	-62	0	-	-
11AX160SISO	Ant1	6985	6985	Minimal	-61.04	1.88	-62.92	-62	0	-	-
11AX160SISO	Ant1	6985	7060	Minimal	-67.23	1.88	-69.11	-62	10	-	-
11AX160SISO	Ant1	6985	6910	ON	-84	1.88	-85.88	-62	-	-	-
11AX160SISO	Ant1	6985	6985	ON	-84	1.88	-85.88	-62	-	-	-
11AX160SISO	Ant1	6985	7060	ON	-84	1.88	-85.88	-62	-	-	-

7.2 Test Graph




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 819 of 833


11AX20SISO-Ant 1-6455-Center-6455-OFF




11AX20SISO-Ant 1-6455-Center-6455-OFF



11AX20SISO-Ant 1-6455-Center-6455-Minimal



11AX20SISO-Ant 1-6455-Center-6455-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 820 of 833


11AX20SISO-Ant 1-6695-Center-6695-OFF




11AX20SISO-Ant 1-6695-Center-6695-OFF



11AX20SISO-Ant 1-6695-Center-6695-Minimal



11AX20SISO-Ant 1-6695-Center-6695-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 821 of 833


11AX20SISO-Ant 1-7015-Center-7015-OFF




11AX20SISO-Ant 1-7015-Center-7015-OFF



11AX20SISO-Ant 1-7015-Center-7015-Minimal



11AX20SISO-Ant 1-7015-Center-7015-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 822 of 833


11AX160SISO-Ant 1-6185-Center-6110-OFF




11AX160SISO-Ant 1-6185-Center-6110-OFF



11AX160SISO-Ant 1-6185-Center-6110-Minimal



11AX160SISO-Ant 1-6185-Center-6110-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 823 of 833


11AX160SISO-Ant 1-6185-Center-6185-OFF




11AX160SISO-Ant 1-6185-Center-6185-OFF



11AX160SISO-Ant 1-6185-Center-6185-Minimal



11AX160SISO-Ant 1-6185-Center-6185-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 824 of 833


11AX160SISO-Ant 1-6185-Center-6260-OFF




11AX160SISO-Ant 1-6185-Center-6260-OFF



11AX160SISO-Ant 1-6185-Center-6260-Minimal



11AX160SISO-Ant 1-6185-Center-6260-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 825 of 833


11AX160SISO-Ant 1-6505-Center-6430-OFF




11AX160SISO-Ant 1-6505-Center-6430-OFF



11AX160SISO-Ant 1-6505-Center-6430-Minimal



11AX160SISO-Ant 1-6505-Center-6430-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 826 of 833


11AX160SISO-Ant 1-6505-Center-6505-OFF




11AX160SISO-Ant 1-6505-Center-6505-OFF



11AX160SISO-Ant 1-6505-Center-6505-Minimal



11AX160SISO-Ant 1-6505-Center-6505-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 827 of 833


11AX160SISO-Ant 1-6505-Center-6580-OFF




11AX160SISO-Ant 1-6505-Center-6580-OFF



11AX160SISO-Ant 1-6505-Center-6580-Minimal



11AX160SISO-Ant 1-6505-Center-6580-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 828 of 833


11AX160SISO-Ant 1-6825-Center-6750-OFF




11AX160SISO-Ant 1-6825-Center-6750-OFF



11AX160SISO-Ant 1-6825-Center-6750-Minimal



11AX160SISO-Ant 1-6825-Center-6750-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 829 of 833


11AX160SISO-Ant 1-6825-Center-6825-OFF




11AX160SISO-Ant 1-6825-Center-6825-OFF



11AX160SISO-Ant 1-6825-Center-6825-Minimal



11AX160SISO-Ant 1-6825-Center-6825-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 830 of 833


11AX160SISO-Ant 1-6825-Center-6900-OFF




11AX160SISO-Ant 1-6825-Center-6900-OFF



11AX160SISO-Ant 1-6825-Center-6900-Minimal



11AX160SISO-Ant 1-6825-Center-6900-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 831 of 833


11AX160SISO-Ant 1-6985-Center-6910-OFF




11AX160SISO-Ant 1-6985-Center-6910-OFF



11AX160SISO-Ant 1-6985-Center-6910-Minimal



11AX160SISO-Ant 1-6985-Center-6910-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 832 of 833


11AX160SISO-Ant 1-6985-Center-6985-OFF




11AX160SISO-Ant 1-6985-Center-6985-OFF



11AX160SISO-Ant 1-6985-Center-6985-Minimal



11AX160SISO-Ant 1-6985-Center-6985-Minimal




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 833 of 833


11AX160SISO-Ant 1-6985-Center-7060-OFF




11AX160SISO-Ant 1-6985-Center-7060-OFF



11AX160SISO-Ant 1-6985-Center-7060-Minimal



11AX160SISO-Ant 1-6985-Center-7060-Minimal



- End of the Report -