





NTNV\_N78-3450-3550\_PC2\_30\_20\_H\_TID18\_N/  
A\_30\_1000\_#1


NTNV\_N78-3450-3550\_PC2\_30\_20\_H\_TID18\_N/  
A\_1000\_3000\_#1




NTNV\_N78-3450-3550\_PC2\_30\_20\_H\_TID18\_N/  
A\_3000\_12000\_#1

NTNV\_N78-3450-3550\_PC2\_30\_20\_H\_TID18\_N/  
A\_12000\_20000\_#1











NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID5\_N/A  
\_0.009\_0.15\_#1


NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID5\_N/A  
\_0.15\_30\_#1




NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID5\_N/A  
\_30\_1000\_#1

NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID5\_N/A  
\_1000\_3000\_#1









NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID6\_N/A  
\_3000\_12000\_#1



NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID6\_N/A  
\_12000\_20000\_#1





NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID16\_N/  
A\_0.009\_0.15\_#1



NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID16\_N/  
A\_0.15\_30\_#1











NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID17\_N/  
A\_30\_1000\_#1


NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID17\_N/  
A\_1000\_3000\_#1




NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID17\_N/  
A\_3000\_12000\_#1

NTNV\_N78-3450-3550\_PC2\_30\_40\_L\_TID17\_N/  
A\_12000\_20000\_#1












NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID4\_N/A  
\_0.009\_0.15\_#1





NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID4\_N/A  
\_0.15\_30\_#1





NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID4\_N/A  
\_30\_1000\_#1




NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID4\_N/A  
\_1000\_3000\_#1









NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID5\_N/A  
\_3000\_12000\_#1





NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID5\_N/A  
\_12000\_20000\_#1





NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID6\_N/A  
\_0.009\_0.15\_#1



NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID6\_N/A  
\_0.15\_30\_#1









NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID16\_N/  
A\_30\_1000\_#1

NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID16\_N/  
A\_1000\_3000\_#1



NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID16\_N/  
A\_3000\_12000\_#1



NTNV\_N78-3450-3550\_PC2\_30\_40\_M\_TID16\_N/  
A\_12000\_20000\_#1

