




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID16\_N/  
 A\_0.009\_0.15\_#1





NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID16\_N/  
 A\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID16\_N/  
 A\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID16\_N/  
 A\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID16\_NV/  
A\_3000\_12000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID16\_NV/  
A\_12000\_20000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID17\_NV/  
A\_0.009\_0.15\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID17\_NV/  
A\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID17\_NV/  
A\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID17\_NV/  
A\_1000\_3000\_#1






NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID17\_N/A\_3000\_12000\_#1

NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID17\_N/A\_12000\_20000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID18\_N/A\_0.009\_0.15\_#1


NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID18\_N/A\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID18\_NV/  
A\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID18\_NV/  
A\_1000\_3000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID18\_NV/  
A\_3000\_12000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_M\_TID18\_NV/  
A\_12000\_20000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID4\_N/A  
\_0.009\_0.15\_#1


NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID4\_N/A  
\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID4\_N/A  
 \_30\_1000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID4\_N/A  
 \_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID4\_N/A  
 \_3000\_12000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID4\_N/A  
 \_12000\_20000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID5\_N/A  
\_0.009\_0.15\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID5\_N/A  
\_0.15\_30\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID5\_N/A  
\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID5\_N/A  
\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID5\_N/A  
\_3000\_12000\_#1


NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID5\_N/A  
\_12000\_20000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID6\_N/A  
 \_0.009\_0.15\_#1





NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID6\_N/A  
 \_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID6\_N/A  
 \_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID6\_N/A  
 \_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID6\_N/A  
\_3000\_12000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID6\_N/A  
\_12000\_20000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID16\_N/  
A\_0.009\_0.15\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID16\_N/  
A\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID16\_N/  
A\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID16\_N/  
A\_1000\_3000\_#1











NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID16\_N/  
A\_3000\_12000\_#1

NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID16\_N/  
A\_12000\_20000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID17\_N/  
A\_0.009\_0.15\_#1


NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID17\_N/  
A\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID17\_N/  
A\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID17\_N/  
A\_1000\_3000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID17\_N/  
A\_3000\_12000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID17\_N/  
A\_12000\_20000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID18\_N/  
A\_0.009\_0.15\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID18\_N/  
A\_0.15\_30\_#1







NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID18\_N/A\_30\_1000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID18\_N/A\_1000\_3000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID18\_N/A\_3000\_12000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_90\_H\_TID18\_N/A\_12000\_20000\_#1








NTNV\_N77-3450-3550\_PC2\_30\_100\_L\_TID5\_N/  
A\_0.009\_0.15\_#1

NTNV\_N77-3450-3550\_PC2\_30\_100\_L\_TID5\_N/  
A\_0.15\_30\_#1



NTNV\_N77-3450-3550\_PC2\_30\_100\_L\_TID5\_N/  
A\_30\_1000\_#1

NTNV\_N77-3450-3550\_PC2\_30\_100\_L\_TID5\_N/  
A\_1000\_3000\_#1

